CENTRE FLOOR FRONT CROSS MEMBER: REPLACEMENT



WARNING

DANGER: HIGH VOLTAGE VEHICLE.



Risks of serious burns or electric shocks that may prove fatal.

Before carrying out any work on the vehicle, it is essential that you follow the instructions regarding vehicle lockout. This work must be carried out by an employee who is qualified and authorised to work on a high-voltage onboard network<u>Vehicle:</u>
Precautions for the repair

Lockout the vehicle<u>Vehicle: Lockout - Removal of lockout</u> .

1. COMPOSITION OF THE SPARE PART



No.	Description	Thickness (mm)
(1)	Central floor front cross member closure	1.5
(2)	Outer support reinforcement of front seat mounting	1.47
(3)	Central floor front cross member	1.5
(4)	Inner support reinforcement of front seat mounting	1.5

2. IN THE EVENT OF REPLACEMENT

There is only one way of replacing this part:

■ complete replacement.



CAUTION

If the mating faces of the parts to be welded are not accessible, make EGW plug welds to replace the original resistance welds (see MR 400).

CAUTION

To avoid damaging the vehicles electric and electronic components, the earths of any wiring harness near the weld area must be disconnected.

Position the earth of the welding machine as close as possible to the weld area (see MR 400).

Locate the earths located near to the weld area Earths on body: List and location of components .

1- COMPLETE REPLACEMENT

1)PART IN POSITION





Repair-40x03x08-02x49-1-4-1.xml



XSL version : 3.02 du 22/07/11