

# BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



☎ 01420 477655

@ bteautomotive.co.uk

✉ service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr Frank O'gorman  
6 Eddeys Lane  
Headley Down  
Bordon  
Hampshire  
GU358HU  
Mobile: 07410955305

## Invoice

**58074**

Invoice Date:

Account No:

O,G001

Order Ref:

Payment Date:

Unpaid

Payment Method:

Registration	Make & Model	Chassis Number	Mileage
DK08 YBS	Fiat Sedici	TSMFYB61S00183786	75766
Engine No	Engine Code	Key Code	Fuel Type
			Diesel
Technician			

Carry Out Mot And Rectify Mot Faults As Requested.

- 1) FAIL ENGINE MIL INOPERATIVE OR INDICATES A MALFUNCTION (8.2.2.2 (G))
- 2) FAIL OFFSIDE FRONT POSITION LAMP NOT WORKING (4.2.1 (A))

Rectify Mot Faults As Requested. Remove EGR Blanking Plate. Remove And Replace O/s Front Side Lamp Bulb. Remove And Replace Front Windscreen Wiper Blades.

Carry Out Management System Diagnostics. Interrogate Management System(s), Carry Out Fault Code Recovery. Carry Out Live/ Actual Data Test Protocol, Carry Out Component Testing And Isolate System Fault(s)

Customer Fault(s) Upon Arrival:

Fault Code(s) Recovered: 1) P0400 EGR Flow Rate - Limited. Carry Out Component Testing. Carry Out Live Data Testing. Remove EGR Blanking Plate. Carry Out System Adaptations.

Carry Out BTE Automotive Major Service Schedule

Replacement Of Oil Filter

Replacement Of Cabin Filter

Replacement Of Air Filter

CASTROL™ Digital EHVC 47 Point Service Inspection

Inspection And Adjustment Of All Vehicle Fluid Levels Including:

- Power Steering
- Brake Fluid
- Clutch Fluid
- Coolant
- Transmission Fluid (where Applicable)
- Timing Belt - Renew: Every 90,000 Miles Or 60 Months

### Additional Service Item(s)

Road Test

Re-set Service Light

Stamp Customer's Service Book/ Portfolio And Update Digital Service Record (DSR)

\* THE BRAKE FLUID IS RECOMMENDED TO BE REPLACED IF THE MOISTURE CONTENT EXCEEDS 2%. \*\* REPLACEMENT OF ADDITIONAL FILTERS IS AN OPTIONAL EXTRA AND WILL RESULT IN AN ADDITIONAL COST. \*\*\* ADDITIONAL CHARGE MAY BE APPLICABLE FOR SPECIALIST LUBRICATION (EXCLUDES ACEA C1, C2, C3, C4 AND FORD ECOBOOST SPECIFIC OIL GRADES)



INSTITUTE OF THE  
MOTOR INDUSTRY

# BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



☎ 01420 477655

@ bteautomotive.co.uk

✉ service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr Frank O'gorman  
6 Eddeys Lane  
Headley Down  
Bordon  
Hampshire  
GU358HU  
Mobile: 07410955305

## Invoice

**58074**

Invoice Date:

Account No:

O,G001

Order Ref:

Payment Date:

Unpaid

Payment Method:

MOT	Qty	Status
Carry out MOT Test	1	

Parts	Part No.	Qty	Unit	D	Sub Total
Engine Oil Filter OE FIAT BOSCH	WIXWL7402	1	6.78		6.78
Cabin Filter OE FIAT BOSCH	WIXWP9314	1	13.48		13.48
Air Filter OE FIAT BOSCH	08295266	1	12.77		12.77
Wurth Brake Cleaner Plus 500ml	BRAKE	1	3.95		3.95
Wurth Screen Wash 300ml Orange Zest Concentrate	SCREEN	1	1.97		1.97
Environmental Waste Lubricant Disposal Charge	ENVIRO	1	4.00		4.00
Wurth Oil Sump Washer And Nut (V)	SUMPW	1	2.95		2.95
5w30 Castrol® Gtx® Acea C3 Fully Synthetic Engine Oil	5W30	4.50	10.95		49.28
12v Bosch Pure Light Bulb UK501	BULB501	1	1.85		1.85
BOSCH Super Plus Wiper Blade 24'	SP24	1	10.99		10.99
BOSCH Super Plus Wiper Blade 13"	SP13	1	5.99		5.99

Labour	Qty	Unit	D	Sub Total
12.030 Bte Automotive Major Service Schedule	2	60.00		120.00
- Remove And Replace Oil Filter	1	0.00		0.00
- Drain And Refill Engine Oil	1	0.00		0.00
- Remove And Replace Cabin Filter	1	0.00		0.00
- Remove And Replace Air Filter	1	0.00		0.00
- Carry Out Bte Automotive 47 Point Inspection	1	0.00		0.00
- Refill Windscreen Washer Reservoir	1	0.00		0.00
B13.0001 Remove And Replace Side Lamp Bulb	.1	60.00		6.00
W10023 Remove And Replace Front Windscreen Wiper Blades	.1	60.00		6.00
Management System(S) Interrogation   Bosch Kts Diagnostics	1	49.96		49.96
- Fault Code Interrogation	0	0.00		0.00
- Actual Data/ Live Data Test Procedures Or Protocol	0	0.00		0.00
- Carry Out Component Test Procedure(S)	0	0.00		0.00
- Isolate System Fault(S) And/ Or Component Fault(S)	0	0.00		0.00



INSTITUTE OF THE  
MOTOR INDUSTRY

# BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



☎ 01420 477655

@ bteautomotive.co.uk

✉ service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr Frank O'gorman  
6 Eddeys Lane  
Headley Down  
Bordon  
Hampshire  
GU358HU  
Mobile: 07410955305

## Invoice

**58074**

Invoice Date:

Account No:

O,G001

Order Ref:

Payment Date:

Unpaid

Payment Method:

### Advisories

Battery Performance: 40%

Alternator Charging Performance: 14.03v

Coolant Performance: -29o (Overfull)

Brake Fluid Performance: 1% (2%> Replacement At Next Service Interval)

Front Brake Pads Are Worn: 40%

Front Brake Discs Are Worn: 40%

Lhf Tyre Is Worn Down To: 7.50 Mm

Rhf Tyre Is Worn Down To: 8.00 Mm

Lhr Tyre Is Worn Down To: 6.00 Mm

Rhr Tyre Is Worn Down To: 5.00mm (Damaged)

Tyre Size: 205/60R16

Brake Drums Installed On This Model

Timing Belt Renew: Every 90,000 Miles Or 60 Months

~~Windscreen Wiper Blade Defective Worn (3.4 (B) (I))~~

Offside Front Lower Suspension Arm Pin Or Bush Worn But Not Resulting In Excessive Movement (5.3.4 (A) (I))

Nearside Front Upper Macpherson Strut Pin Or Bush Worn But Not Resulting In Excessive Movement Noisy (5.3.4 (A) (I))

Front Brake Hose Has Slight Corrosion To Ferrule Offside & Nearside (1.1.12 (F) (I))

Rear Oil Leak, But Not Excessive Differential (8.4.1 (A) (I))

Rear Brake Hose Has Slight Corrosion To Ferrule Offside & Nearside (1.1.12 (F) (I))

Rear Coil Spring Corroded Offside & Nearside (5.3.1 (B) (I))

Nearside Obligatory Mirror Slightly Loose (3.3 (B) (I))

More Information About Our Services We Offer Including Our Business Terms And Conditions Can Be Found By Visiting  
[bteautomotive.co.uk](http://bteautomotive.co.uk)

+



INSTITUTE OF THE  
MOTOR INDUSTRY



# BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



☎ 01420 477655

@ bteautomotive.co.uk

✉ service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr Frank O'gorman  
6 Eddeys Lane  
Headley Down  
Bordon  
Hampshire  
GU358HU  
Mobile: 07410955305

## Invoice

**58074**

Invoice Date:

Account No:

O,G001

Order Ref:

Payment Date:

Unpaid

Payment Method:

All New Replacement Components Are Covered By A Minimum 12 Month/ 12,000 Mile Warranty.

We Would Love To Hear From You!

visit [bteautomotive.co.uk/feedback](http://bteautomotive.co.uk/feedback)

Labour	181.96
Parts	114.01
<b>SubTotal</b>	<b>295.97</b>
VAT (20%)	59.20
MOT	54.85
<b>Total</b>	<b>410.02</b>
<b>Balance</b>	<b>410.02</b>



INSTITUTE OF THE  
MOTOR INDUSTRY

	<b>Date</b>	:28/01/19 16:11
	<b>Order no.</b>	:
	<b>Registration</b>	:
	<b>VIN</b>	:
	<b>Mileage</b>	:
	<b>First registrat.</b>	:
<b>Customer no.</b>	<b>Fitter</b>	:TAH
<b>Tel.(private)</b>	<b>Telephone</b>	:
<b>Tel.(business)</b>	<b>Fax</b>	:01420478771

FIAT,Sedici [189], Sedici 1.9 JTD 4x4, Diesel, 1.9, 88.0kw, 05/2006 - 09/2009, D19AA

**Diesel EDC 16C39 CF4 V3**

**28/01/19 16:15**

1. Error memoryNumber of errors: 1 16:15

P0401	Exhaust-gas recirculationsolenoid valve	Valve stuck in closed position
-------	---	--------------------------------

2. Actuators 16:15

3. Function tests 16:16

4. Adjustments / settings 16:16

5. Reset lubrication service 16:16

6. Special functions 16:16

7. Actuators 16:16

8. Error memory 16:17

9. Erase error memory 16:18

Error memory was deleted.

10. Error memoryNumber of errors: 0 16:18

Remarks: egr blanking plate removed, adaption complete

Date

Signature



# MOT test certificate

① Vehicle identification number

**TSMFYB61S00183786**

②a Registration number

**DK08YBS**

②b Country of registration

**GB**

Make and model

**FIAT SEDICI**

⑤ Vehicle category

**M1**

④ Mileage

**75,769 miles**

Mileage history

**69,133 miles** 19.01.2018

**64,677 miles** 10.01.2017

**60,566 miles** 14.01.2016



**Driver & Vehicle  
Standards  
Agency**

## ⑦ Pass with defects

## ⑥ Repair as soon as possible (minor defects)

- Windscreen wiper blade defective (worn) [3.4 (b) (i)]
- Obligatory mirror slightly loose Nearside [3.3 (b) (i)]
- Obligatory mirror slightly damaged Nearside [3.3 (b) (i)]

## Monitor and repair if necessary (advisories)

- Suspension arm pin or bush worn but not resulting in excessive movement Offside Front Lower [5.3.4 (a) (i)]
- Macpherson strut pin or bush worn but not resulting in excessive movement Nearside Front Upper (noisy) [5.3.4 (a) (i)]
- Brake hose has slight corrosion to ferrule Front (offside & nearside) [1.1.12 (f) (i)]
- Oil leak, but not excessive Rear (differential) [8.4.1 (a) (i)]
- Brake hose has slight corrosion to ferrule Rear (offside & nearside) [1.1.12 (f) (i)]
- Coil spring corroded Rear (offside & nearside) [5.3.1 (b) (i)]

③b Date of the test

**28.01.2019**

⑧ Expiry date

**27.01.2020**

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 28.12.2019.

③a Location of the test

**UNIT 34, WOOLMER TRADING ESTATE, BORDON, GU35 9QF**

⑨ Testing organisation and inspector name

**0937AQ BTE AUTOMOTIVE LTD  
T. E. NICHOLSON**

MOT test number

**3773 9024 3327**

Check that this document is genuine by visiting **[www.gov.uk/check-mot-history](http://www.gov.uk/check-mot-history)**

If any of the details are not correct, please contact DVSA by email at **[enquiries@dvsa.gov.uk](mailto:enquiries@dvsa.gov.uk)** or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at **[www.gov.uk/mot-reminder](http://www.gov.uk/mot-reminder)** or by telephone on 0300 1239000.



# Refusal of MOT test certificate

① Vehicle identification number

**TSMFYB61S00183786**

②a Registration number

**DK08YBS**

②b Country of registration

**GB**

Make and model

**FIAT SEDICI**

⑤ Vehicle category

**M1**

④ Mileage

**75,766 miles**

75,769



**Driver & Vehicle  
Standards  
Agency**

## ⑦ Fail

### ⑥ ~~Repair immediately (major defects)~~

- Engine mil inoperative or indicates a malfunction [8.2.2.2 (g)]
- Position lamp not working Offside Front [4.2.1 (a)]

### ⑥ ~~Repair as soon as possible (minor defects)~~

- Windscreen wiper blade defective (worn) [3.4 (b) (i)]
- Obligatory mirror slightly loose Nearside [3.3 (b) (i)]
- Obligatory mirror slightly damaged Nearside [3.3 (b) (i)]

### Monitor and repair if necessary (advisories)

- Suspension arm pin or bush worn but not resulting in excessive movement Offside Front Lower [5.3.4 (a) (i)]
- Macpherson strut pin or bush worn but not resulting in excessive movement Nearside Front Upper (noisy) [5.3.4 (a) (i)]
- Brake hose has slight corrosion to ferrule Front (offside & nearside) [1.1.12 (f) (i)]
- Oil leak, but not excessive Rear (differential) [8.4.1 (a) (i)]
- Brake hose has slight corrosion to ferrule Rear (offside & nearside) [1.1.12 (f) (i)]
- Coil spring corroded Rear (offside & nearside) [5.3.1 (b) (i)]

③b Date of the test

**28.01.2019**

③a Location of the test

**UNIT 34, WOOLMER TRADING ESTATE, BORDON, GU35 9QF**

⑨ Testing organisation and inspector name

**0937AQ BTE AUTOMOTIVE LTD  
T. E. NICHOLSON**

MOT test number

**3784 6825 9556**



To find out about retests, or if you disagree with the test result, see the fees and appeals poster at the vehicle testing station. Alternatively, visit

**[www.gov.uk/getting-an-mot](http://www.gov.uk/getting-an-mot)**

If any of the details are not correct, please contact DVSA by email at **[enquiries@dvsa.gov.uk](mailto:enquiries@dvsa.gov.uk)** or by telephone on 0300 1239000.

Find out about the vehicle's MOT history at **[www.gov.uk/check-mot-history](http://www.gov.uk/check-mot-history)**