

BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



01420 477655

@ bteautomotive.co.uk

service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr O,Gorman
6 Eddeys Lane
Headley Down
Bordon
Hampshire
GU358HU
Mobile: 07410955305

Invoice

57486

Invoice Date: 20/12/2018
Account No: O,G001
Order Ref:
Payment Date: 20/12/2018
Payment Method: Mastercard

Registration	Make & Model	Chassis Number	Mileage	
DK08 YBS	Fiat		75302	
Engine No	Engine Code	Key Code	Fuel Type	Technician

Carry Out Puncture Repair To Lhf Tyre Including Replacement Tyre Valve And Wheel Balance.

Tyre Repairable - No Tyre Tread Illegal

Cause Of Puncture - Screw In Tread

Tyre Size - 205601692h

Tyre Manufacturer And Tread Pattern -

Tyre Speed Rating And Load Index - 92h

Remove And Replace Front Tyres.

Carry Out Front Wheel Alignment Service. Carry Out Adjustment To Within Manufacturers Specification(s) And Recommendations.

Parts	Eco	WGrip	dB	Part No.	Qty	Unit	D	Sub Total
Tr13 Rubber Tyre Valve				VALVE	2	2.00		4.00
Bosch Aluminium Wheel Balance Per Wheel				ALUBAL	2	4.50		9.00
Environmental Tyre Casing Disposal Charge (Each)				ENVIROTYRE	2	2.00		4.00
205/60R16 92V HP5 MAXXIS	C	A	70		2	52.58		105.16

Labour	Qty	Unit	D	Sub Total
Puncture Repair Including Wheel Balance	1	0.00		0.00
T1.2003 Tyre Installation Front Road Tyres	1	0.00		0.00
W1.2001 Hoffmann Megaplan Ecoline Wheel Alignment Service	1	33.29		33.29

Please Check Wheel Nuts For Tightness After 50 Miles
Please Ensure All Wheel Covers Are Correctly Installed Before Leaving

bteautomotive.co.uk



BTE AUTOMOTIVE LTD

Unit 34 & 44 Woolmer Trading Estate, Bordon, Hampshire, GU35 9QF



☎ 01420 477655

@ bteautomotive.co.uk

✉ service@bteautomotive.co.uk

Vat No: 544234460 Ltd Company No: 5031357

Connect with us.



Mr O,Gorman
6 Eddeys Lane
Headley Down
Bordon
Hampshire
GU358HU
Mobile: 07410955305

Invoice

57486

Invoice Date: 20/12/2018
Account No: O,G001
Order Ref:
Payment Date: 20/12/2018
Payment Method: Mastercard

All New Replacement Components Are Covered By A Minimum 12 Month/ 12,000 Mile Warranty.

We Would Love To Hear From You!

visit bteautomotive.co.uk/feedback

PAID IN FULL

Labour	33.29
Parts	122.16
SubTotal	155.45
VAT (20%)	31.09
Total	186.54
Receipts	186.54
Balance	0.00



INSTITUTE OF THE
MOTOR INDUSTRY

Measuring report

BTE Automotive

01420 477655

Customer name	Gorman	Measuring date	20-12-2018 17:01:03
License plate	DK08 YBS	Mileage	
Vehicle manufacturer	Fiat	Operator	
Vehicle model	16V		



	Min	Mid	Max	L	R	L	R
Front	Specifications			Readings before		Readings after	
Caster	+1.67°	+3.67°	+5.67°	----	----	----	----
Kingpin	----	----	----	----	----	----	----
Camber	-1.38°	-0.38°	+0.62°	+0.00°	+0.45°	+0.09°	+0.33°
Individual toe	+0.00°	+0.04°	+0.07°	-0.36°	-1.15°	+0.03°	+0.02°
Total toe	+0.00°	+0.07°	+0.14°		-1.51°		+0.05°
Setback					-0.10°		+0.04°
Included angle	-1.38°	-0.38°	+0.62°	-----	-----		
Toe-out on turn				----			
Max. turn angle				-----	-----	-----	-----
Rear	Specifications			Readings before		Readings after	
Camber	----	----	----				
Individual toe	----	----	----				
Total toe	----	----	----				
Setback							
Thrust angle							